






Colour Reference Chart

for all **gke Clean-Record**[®]
ultrasonic cleaning indicators



Indicator has been fully washed off



Indicator has been partially washed off /
Information about ultrasonic cleaning efficacy



Indicator has NOT been washed off



Level 1 (yellow)

Level 2 (green)

Level 3 (blue)

Level 4 (red)